SNOW ENGINEERING CO. Wichita Falls, Texas		ENGINEERING REPORT ORDER				NUMBER 01				
TITLE SERVICE LETTER INDEX		BY Leland Snow CHK'D				MODEL All				
		DATE *2/8/17				SERIAL All				
						PAGE 1 OF 11*				
		APPLICABILITY								
S/L No.	SUBJECT	300 301	302 302A	400 400A	401 401B	402 402A 402B	501	502 502A 502B 503A	602	802 802A
1-18	Incorporated in all aircraft.									
19	Wire Deflector Cable (Thru 0060)	X								
20	Rudder Pedal Support Tube (Thru 0067)	X								
21	Battery Cable thru Firewall (Thru 0040)	X								
22	Park brake Valve (0061 thru 0112)	X	X							
23	Battery Cable thru Firewall (Thru 0100)	X								
24	Not Applicable.									
25	Back-fire door hinge (Thru 0037)	X								
26	Bolts thru fin front spar attach	X	X	X						
27	Bolts thru wing rear spar/fuselage	X	X	X						
28	Main and tail gear bolts	X	X							
29	Eye bolt top of master cylinder (Thru 0112)	X	X							
30	Wire deflector cable (Thru 0107)	X								
31	Cover plate under wing spar	X	X	X						
32	Alternator housing (Thru 0161)	X								
33	Induction hose on carburetor	X								
34	Tail gear spring	X								
35	Flap actuator Micro-Switches (Thru 0160)	X	X							
35A	Not Applicable.	X								
36	Wing attach angle Install. (Thru 0217)	X	X							
37	Cracks in lower longerons (Thru 0240)	X	X							
38	Wing rear-spar attach to fuselage (Thru 0224)	X	X							
39	Brake master cylinders (Thru 0216)	X	X							
40	Hopper removal and inspection	X	X	X						
41	Park brake valve (0061 thru 0358)	X	X	X						
42	Elevator counterweights (Thru 0300)	X	X	X						
43	Ring cowl attach lugs	X								
44	Emergency Egress (Thru 0433)	X	X	X						
45	Main Landing Gears	X	X	X						
45A	Fuselage Bushings-stab. (Thru 0434)	X	X	X						
46	Baggage Door Placard (Thru 0460)	X	X	X						
47	Fuselage Fitting-Fin Attach (Thru 0240)	X	X							
48	Rudder Hinges (Thru 0260)	X	X							
49	Brake hose attach at wheel (Thru 0241)	X	X							
50	Engine mount ring and bolts	X								
51	Flap Microswitches (Thru 0369)	X	X	X						
52	Hopper lid seal material (Thru 0475)	X	X	X						
53	Alternate Induction Elbow (Thru 0470)	X								

SNOW ENGINEERING CO. Wichita Falls, Texas	ENGINEERING REPORT ORDER	NUMBER 01
		MODEL All
TITLE SERVICE LETTER INDEX	BY CHK'D Leland Snow	SERIAL All
	DATE * 1/20/04	PAGE 2 OF *

S/L No.	SUBJECT	300 301	302 302A	400 400A	401 401B	402 402A 402B	501	502 502A 502B 503A	602	802 802A	
		APPLICABILITY									
54	Ring Cowl Attach Lugs	X									
55	Wing Lower Spar Cap Splice Rework	X									*
55A	Engine Forward Fireshield (Thru 0516)			X							
55B	Battery Drain Sump (Thru 0613)			X							
56	Main Landing gear spring	X		X							
57	Main Landing gear clamp block	X	X	X	X	X	X	X			
58	Main Landing gear axle bolts	X	X	X	X	X	X	X			
59	Fuselage Frame Cracks Upr. Engine Mount	X									
60	Vertical Fin Rib Cracks (0261-0640)	X		X							
61	Primer Line Cracks	X									
62	Horizontal Stabilizer Eyebolts (Thru 0634)	X	X	X							
63	Aft Fuselage Diagonal Tube	X	X	X	X						
64	Shoulder Harness (Thru 0630)	X	X	X							
65	Rudder-Aileron Interconnect (0634)	X	X	X							
66	Installation of 40007-3 Gears	X	X	X							
67	Industrial Battery Replacement	X									
68	Precision Aero Ring Cam for R1340	X									
69	Cracks in Wing Attach Tube (Thru 0666)	X	X	X	X						
70	Wing Lower Spar Cap Splice Rework	X									*
70A	Prop Tip Separation	X									
71	Nuts on Main Gear Axle Bolts (Thru 0679)	X	X	X	X						
72	Vertical Fin Attach Plate (Thru 0240)	X	X								
72A	All Metal Elevator Installation (0001 thru 0673)	X	X	X							
73	Propeller Tip Separations	X			X						
73A	VR1528-11 Voltage Control (400-0609 thru 0699 502-0001 thru 0030)			X				X			
74	Speed Ring Flexible Mounting (301/401 thru 0699), (501 thru 0030)	X			X		X				
75	Hour Meter Recording Rate	X			X		X				
76	Parking Brake Valve	X	X	X	X	X	X	X			
77	Rudder Cable Inspection	X	X	X	X	X	X	X	X	X	
78	Brake Master Cylinder Installation	X	X	X	X		X	X			
79	Fuel Hose Deterioration	X			X		X				
80	Oil Cooler Ejector (Thru 0030)							X			
81	No longer applicable										*
82	Brake Master Cylinder Eyebolt	X			X	X	X	X			

* Indicates Revision

SNOW ENGINEERING CO. Wichita Falls, Texas		ENGINEERING REPORT ORDER									NUMBER 01
TITLE SERVICE LETTER INDEX		BY Leland Snow CHK'D									MODEL All
		DATE *1 /28 /14									SERIAL All
											PAGE 3 OF
		APPLICABILITY									
S/L No.	SUBJECT	300 301	302 302A	400 400A	401 401B	402 402A 402B	501	502 502A 502B 503A	602	802 802A	
83	Vertical Fin Spar Attach Bolts				X	X	X	X			
84	Spray Pump Fan Blade Failure	X			X		X				
85	Carbon Pile Electrical System					X		X			
86	Flexibile Speed Ring Attach Straps	X			X		X				
87	Vertical Fin Rear Spar	X	X	X	X	X	X	X			
88	Vertical Fin Rib Cracks (Thru 0380)	X	X	X							
89	Wing Attach Angles	X	X	X	X	X	X	X			
89A	Wing Attach Angles	X		X	X	X	X	X			
90	Extreme Corrosion on Spar Caps	X	X	X							
91	Airspeed Limits on Turbine Models		X	X		X		X			
92	Cracks at Wing Attach Tube Bushing						X	X			
93	Corrosion In Horizontal Stabilizer Brace Rivets	X	X	X	X						
94	Cleveland 40-133 Wheel Bolts				X	X	X	X			
95	Wing Skin Rivets Main Spar Flange						X	X			
96	Emergency Cockpit Door Release	X	X	X	X	X	X	X			
97	Cockpit Overturn Skid Plate	X	X	X	X	X	X	X	X	X	*
98	Corrosion on Stabilizer Internal Brace	X	X	X	X	X	X	X	X	X	
99	Corrosion on Wing Rear Spar Caps	X	X	X							
100	Rudder-Aileron Interconnect Cables	X		X	X	X					
101	FCU Manual Override Kit Availability					X		X			
102	Cockpit Heater			X		X		X			
103	Control Stick Yoke Bolt	X	X	X	X	X	X	X			
104	Main Landing Gear Service Life	X	X	X	X	X	X	X			
104A	Landing Gear Failure, p/n 40091-2									X	
105	Fiberglass Elbow in Engine Induction System	X			X		X				
106	Start Lever Control Lock Spring					X		X			
107	Parking Brake Valve	X	X	X	X	X	X	X			
108	Battery Restraint	X			X		X				
109	Spray Plumbing	X	X	X	X	X	X	X			
110	Main Wheel Bearings				X	X	X	X			
110A	Pratt & Whitney PT6A-45R Engine Accessory Gearbox Coupling Shaft Decoupling (Thru 0192)							X			
111	Fuel Filter Warning Light		X	X		X		X			
112	Step Cracks	X	X	X	X	X	X	X			
113	Flexible Speed Ring Attach Straps	X			X		X				
114	Spray Plumbing	X	X	X	X	X	X	X			
115	Collins Air Conditioner Installation	X	X	X	X	X	X	X			
115A	Engine Forward Fireshield Ring Attach Brackets							X			
116	Extreme Spar Cap Corrosion	X	X	X							

* Indicates Revision

SNOW ENGINEERING CO. Wichita Falls, Texas	ENGINEERING REPORT ORDER	NUMBER 01
		MODEL All
TITLE SERVICE LETTER INDEX	BY Leland Snow CHK'D	SERIAL All
	DATE 12/21/07	PAGE 4 OF *

S/L No.	SUBJECT	APPLICABILITY								
		300 301	302 302A	400 400A	401 401B	402 402A 402B	501	502 502A 502B 503A	602	802 802A
117	Landing Gear Bolt Replacement	X	X	X	X	X	X	X		
118	Hopper Removal & Inspection			X	X	X	X	X		
119	Tail Spring Replacement	X	X	X	X	X	X	X		
120	Oil Cooler Blower Availability							X		
121	Prop Cable Lock Washers		X	X		X		X		
122	Ignition Switch	X			X		X			
123	Ignition Switch	X			X		X			
123A	Cracked Py Air Line on PT6A-45R Engines							X		X
123B	APU Receptacle				X					
124	Metal in Oil Contamination	X	X	X	X	X	X	X	X	X
125	Low Oil Pressure Warning Light							X		X
126	PT6A Engine Oil Scavenge Tubes			X		X		X	X	X
126A	PT6A-45R Engine Vibration							X		X
126B	APU Receptacle							X		
126C	Not Applicable									
127	Vertical Fin Front Spar	X	X	X	X	X	X	X		
128	FCU Air Purge in PT6 Engines			X		X		X		X
129	Horizontal Stab. Attach Eyebolts	X	X	X	X				X	X
129A	Horizontal Stab. Attach Eyebolts								X	X *
129B	Horizontal Stab. Attach Eyebolts	X		X					X	X
130	Automatic Flagman Installation	X	X	X	X	X	X	X	X	X
131	PFT Generator Control Unit		X	X		X		X		X
132	Stewart Warner Hobbs Pressure Switches	X	X	X	X	X	X	X		X
133	Extend C.G. Limits on AT's Retrofitted with all - metal Elevators and Rudder	X	X	X						
134	R1340 Crankshaft Counterweight Cracking	X			X					
135	R1340 Crankshaft Counterweight Cracking	X			X					
136	R1340 Crankshaft Counterweight Cracking	X			X					
137	Turbine Fuel Filters		X	X		X		X	X	X
137A	Gate Stop Position Indicator							X		X
138	Vertical Fin Front and Rear Spar Failure		X	X		X		X		
139	Not Applicable.									
140	Flap System Travel Overrun	X	X	X	X	X	X	X		
141	Left Side Oil Cooler Platform Step		X	X		X		X		X
142	Hopper Rinse System Check Valve	X		X	X	X	X	X		X
143	Turbine Oil Cooler							X		X
144	Vertical Fin Rib Cracking	X	X	X						
145	Main Wing Spar Replacement (Not Applicable)									
146	Aft Fuselage Failures (Apply to 802, 802A only)									X
147	Equipment Mounted Under the Seat	X	X	X	X	X	X	X	X	X

* Indicates Revision

SNOW ENGINEERING CO. Wichita Falls, Texas	ENGINEERING REPORT ORDER	NUMBER 01
TITLE SERVICE LETTER INDEX	BY Leland Snow CHK'D	MODEL All
	DATE *12/30/19	SERIAL All
		PAGE 5 OF

S/L No.	SUBJECT	300 301	302 302A	400 400A	401 401B	402 402A 402B	501	502 502A 502B 503A	602	802 802A	
	APPLICABILITY										
148	Fuel Contamination	X	X	X	X	X	X	X	X	X	*
149	Engine Driven Air Conditioner Compressor					X		X		X	
150	Aileron Rudder Interconnect System									X	
151	Main Landing Gear Installation									X	
152	Shoulder Harness	X	X	X	X	X	X	X	X	X	
153	Emergency Cockpit Door Release	X	X	X	X	X	X	X		X	
154	Hallett Fuel Valve	X			X	X	X	X		X	
155	Vertical Fin Front Spar Fitting	X	X	X	X	X	X	X			
156	Rudder Pedals	X	X	X	X	X	X	X		X	
157	PT6 Engine Oil Fill Tube			X		X		X			
158	A/C Compressor Drive Pad Spline Lubrication					X		X	X	X	
159	Retrofit of Air Conditioner to R134a Refrigerant					X		X	X	X	
160	Main Landing Gear Axle Failure	X	X	X	X						
161	Service Life On Aluminum Lower Spar Caps	X	X	X							
162	Curtis Quick Drain Valves/Wings & Header Tank	X	X	X	X	X	X	X	X	X	
163	L.E. Skin Cracks at Attachment to Nose Ribs	X		X		X		X			
164	High Rate Filling of Hopper	X	X	X	X	X	X	X	X	X	
165	Flap Actuator Jack Screw Failure	X	X	X	X	X	X	X			
166	Brake Master Cylinder Eyebolt	X	X	X	X	X	X	X	X	X	
167	PT6A P3 Air Filter Maintenance			X		X		X	X	X	
168	Air Conditioner Compressor Clutch					X		X	X	X	
169	Tail Spring Clamp Block Bolts	X	X	X	X	X	X	X	X	X	
170	Air Conditioner Drive Pad					X		X	X	X	
171	Tail Wheel Lock Bushing Repair	X	X	X	X	X	X	X	X	X	
172	Beta Valve Plunger Sticking			X		X		X	X	X	
173	PT6A FCU To Fuel Nozzle Manifold Fuel Line Chafing							X	X	X	
174	Turbine Fuel Filter					X		X		X	
175	Rudder-Aileron Interconnect Cables	X	X	X	X	X	X	X			
175A	Rudder Horn Cracking (0001-0042)									X	
176	Vertical Fin Rib Cracking	X	X	X							
177	A/C Drive Pad to AGB Housing Interference					X		X			
178	Imbalance of Fuel in Fuel Tanks	X	X	X	X	X	X	X	X	X	
178A	Recommendations to Prevent Fuel Imbalance...	X	X	X	X	X	X	X	X	X	
179	Air-Conditioner Evaporator-Blower Motor					X		X	X	X	
180	Horizontal Stabilizer Attaching Pedestal	X	X	X	X	X	X	X	X	X	
180A	Horizontal Stabilizer Attaching Pedestal	X	X	X	X	X	X	X	X	X	
181	R-12 Air-Cond.-Compressor Clutch Replacement					X		X	X	X	
182	AT-502 Firewall-Forward Hopper-Rinse-Tank Support Brkt.							X			
182A	AT-502 Firewall-Forward Hopper-Rinse-Tank Support Brkt.							X			

* Indicates Revision

SNOW ENGINEERING CO. Wichita Falls, Texas	ENGINEERING REPORT ORDER	NUMBER 01
		MODEL All
TITLE SERVICE LETTER INDEX	BY Leland Snow CHK'D	SERIAL All
	DATE * 2/8/17	PAGE 6 OF *

S/L No.	SUBJECT	APPLICABILITY								
		300 301	302 302A	400 400A	401 401B	402 402A 402B	501	502 502A 502B 503A	602	802 802A
183	Wing Main Spar Web Flange Cracks					X		X		
184	Flap Actuator Relays				X	X		X	X	X
185	AT-802 Wing Fatigue Life Increase (thru 0059)									X
186	Aileron Stop Bracket Redesign (thru 0083)									X
187	Vertical Fin Front Spar Fitting							X	X	X
188	Wing Rear Spar Bushing Installation (thru 0091)									X
189	Oil Cooler Thermostat					X		X	X	X
190	Rudder Cables						X	X	X	X
191	Emergency Door Release	X	X	X	X	X	X	X	X	X
192	Reduction in Wing Fatigue Life due to Winglet Install.	X	X	X	X	X	X	X		
193	Fuel Control Unit Purge Lines							X	X	X
194	Upper Bolt through Wing Attach Angles...							X		
195	Upper Longeron Failures in Aft Fuselage Structure				X	X	X	X	X	X
195A	Upper Longeron Failures in Aft Fuselage Structure						X	X		
195B	Upper Longeron Failures in Aft Fuselage Structure						X	X		
196	Vertical Fin Front Spar Failure	X			X		X			
197	Cracks in Lower Spar Caps in AT-502A and Early AT-502 Aircraft						X	X		
198	Inboard end of Stabilizer Strut	X	X	X	X	X	X	X		
199	Rudder Cables									X
200	Rudder Cable to Rudder Control Horn Attach Hdwr.	X	X	X	X	X	X	X	X	X
201	Hopper Fill Vent Ball Switch Shaft Coupler	X	X	X	X	X	X	X	X	X
202	Wing Centersplice Rework for AT-400 Series...			X	X	X				
203	Wing Centersplice Rework for AT-802 Series...									X
204	Wing Centersplice Rework for AT-602 Series...								X	
205	Wing Centersplice Rework for AT-500 Series...						X	X		
206	Safe-Life for Wing Center Splice Connection...			X	X	X	X	X	X	X
207	Brake Torque Plate Reinforcing Plate - 0337-0543								X	
208	Water Immersion	X	X	X	X	X	X	X	X	X
209	Proper Operation of Scott Model 4500A2 ...	X	X	X	X	X	X	X	X	X
210	Power Quadrant		X	X		X		X	X	X
211	Automatic Flagman Nose Support Modification								X	X
212	Electrostatic Discharge Damage of PT6A Engine...			X		X		X	X	X *
213	Superceded by 213A								X	
213A	Upper Longeron Failures in Aft Fuselage Structure								X	
213B	Upper Longeron Failures in Aft Fuselage Structure								X	
214	Tail Gear Springs								X	
215	Eddy Current Inspection Intervals...			X	X	X	X		X	X
216	Flap Inboard Hinge Cracking							X	X	
217	Superceded by 217A									X
217A	Upper Longeron Failures in Aft Fuselage Structure									X
217B	Upper Longeron Failures in Aft Fuselage Structure									X

* Indicates Revision

SNOW ENGINEERING CO. Wichita Falls, Texas	ENGINEERING REPORT ORDER	NUMBER 01
		MODEL All
TITLE SERVICE LETTER INDEX	BY CHK'D Leland Snow	SERIAL All
	DATE *12/21/17	PAGE 7 OF

S/L No.	SUBJECT	APPLICABILITY									
		300 301	302 302A	400 400A	401 401B	402 402A 402B	501	502 502A 502B 503A 504	602	802 802A	
218	Superceded by 218A				X	X					
218A	Upper Longeron Failures in Aft Fuselage Structure				X	X					
218B	Upper Longeron Failures in Aft Fuselage Structure				X	X					
219	Fuel Management/Ferry Fuel Proper Use	X	X	X	X	X	X	X	X	X	
220	Wing Centersplice Inspection	X	X	X							
221	Slow Engine Starts								X	X	
222	Fairleads Installed in Tail Wheel Unlock Rod	X	X	X	X	X	X	X	X	X	
223	Wing Walk Material on Inboard Portion of Flaps					X		X			
224	Main Landing Gear Hardware									X	
225	Cockpit Heater Tubes		X	X		X		X	X	X	
226	Wing Lwr. Spar Cap Splice Rework & Rev. Safe Life	X	X	X							
227	Propeller Over-Speed Governor Control Switch					X		X	X	X	
228	Reserved										
229	Replacement Fuel Filter Element		X	X		X		X	X	X	
229A	Fuel Filter Element Inspection & Maintenance		X	X		X		X	X	X	
230	Reserved										
231	Drain Line From Airframe Fuel Pump	X	X	X		X		X			
232	Horizontal Stabilizer Auxiliary Fins									X	
233	Not for General Distribution-Cold Working						X	X			
234	Not for General Distribution-Cold Working						X	X			
235	Horizontal Stabilizer Brace Tube Assembly								X		
236	Main Landing Gear Attach Tube								X		
237	Plenum Firewall Seal Around Engine Mount Tube								X		
238	Not for General Distribution-Cold Working	X		X	X	X					
239	Not for General Distribution-Cold Working	X		X	X	X					
240	Not for General Distribution-Cold Working								X	X	
241	Not for General Distribution-Cold Working									X	
242	Hand-held Fire Extinguisher In Cockpit	X	X	X	X	X	X	X	X	X	
243	Wing Rear Spar Connection	X	X	X	X	X	X	X	X	X	
244	Not for General Distribution-Cold Working							X	X	X	
245	Not for General Distribution-Cold Working									X	
246	Hartzell Propeller Overhaul Intervals			X		X		X	X	X	
247	Upper Rudder Hinge					X		X	X	X	
248	Inspec. of Hopper Rinse Tank Shelf Attach Angles									X	
249	Recommended Service Life for Rubber Hose	X	X	X	X	X	X	X	X	X	*
250	Not for General Distribution-Cold Working								X		
251	Wing Fatigue Management Requirements							X			
252	Not for General Distribution-Eddy Current Insp								X	X	

* Indicates Revision

SNOW ENGINEERING CO. Wichita Falls, Texas		ENGINEERING REPORT ORDER								NUMBER 01	
										MODEL All	
TITLE SERVICE LETTER INDEX		BY Leland Snow		CHK'D						SERIAL All	
		DATE *1/28/14								PAGE 8 OF	
		APPLICABILITY									
S/L No.	SUBJECT	300 301	302 302A	400 400A	401 401B	402 402A 402B	501	502 502A 502B 503A 504	602	802 802A	
253	Rev. C Engine Mount Cracking			X		X		X	X	X	
254	Not for Gen. Distrib.-Optional Ram Air Inlet Sys									X	
255	Not for Gen. Distrib.-Optional Ram Air Inlet Sys								X		
256	Procedures, Emergency & Normal	X	X	X	X	X	X	X	X	X	
257	Engine Inlet Air Filter Cleaning & Replacement			X		X		X	X	X	
258	Dents in Turbine Exhaust Pipes		X	X		X		X	X	X	
259	Engine Fuel & Control-Fuel Control Unit(FCU)								X	X	
	Change CDP Bellows & Py Orifice										
260	Flap Actuator Coupling	X	X	X	X	X	X	X	X	X	
261	P3 Air Pressure Tube Fracture									X	
262	GPS Installations							X	X	X	
263	Not for Gen. Distrib.-Main Wing Spar Cap Rpl.									X	
264	Not for Gen. Distrib.-Main Wing Spar Cap Rpl.									X	
265	Spray Plumbing Safety Strap								X	X	
266	Visual Inspection and Repair of Cracked									X	
	11029-10 Aft Fuselage Tube										
267	Main Landing Gear Attach Tube							X			
268	Reserved										
269	Flap Torque Tube Plate Cracks			X		X		X			
270	Additional Header Tank Drain for Fireboss 802									X	
271	Not for Gen. Distrib.-Retrofit Installation of							X			
	Optional Ram Air Inlet System										
272	Not for Gen. Distrib.-Retrofit Installation of					X					
	Optional Ram Air Inlet System										
273	Reserved										
274	Rudder-Aileron Interconnect Cable Shields									X	
275	Inspection for Wing Leading Edge Rib Cracks									X	
276	Installation of Optional 3/8" Thick Windshield				X	X		X	X	X	*
277	AmSafe Airbag Installation Instructions	X	X	X	X	X	X	X	X	X	
278	Not for Gen.Distrib-Repairs & Treatment of									X	
	Corrosion on Croatian FireBoss										
279	AmSafe Service Letter 23-008			X	X	X	X	X	X	X	
280	Not for Gen-Distrib-Retrofit of 71112 Flap									X	
	Actuator on AT-802/802A Aircraft										
281	Not for Gen-Distrib-9 Hole Attach Block									X	
282	Elevator Counterweight Bolt	X		X	X	X	X	X	X	X	
283	Removal of Baggage Compartment	X	X	X	X	X	X	X	X	X	
284	Wing Inspection & Lower Spar Cap Replace. Times									X	
285	Stabilizer Rear Spar Mount Bracket									X	

* Indicates Revision

SNOW ENGINEERING CO. Wichita Falls, Texas		ENGINEERING REPORT ORDER								NUMBER 01	
										MODEL All	
TITLE SERVICE LETTER INDEX		BY Leland Snow		CHK'D						SERIAL All	
		DATE *12/21/17								PAGE 9 OF	
		APPLICABILITY									
S/L No.	SUBJECT	300 301	302 302A	400 400A	401 401B	402 402A 402B	501	502 502A 502B 503A 504	602	802 802A	
286	Fuel Filter Element Inspection and		X	X		X		X	X	X	
	Maintenance										
287	Rerouting Nose Light Wires					X		X	X	X	
288	Retrofitting Brackett Foam Air Filter to					X		X			
	Existing Ram Air Systems										
289	Retrofitting Brackett Foam Air Filter to								X	X	
	Existing Ram Air Systems										
290	Reserved										
291	Reserved										
292	Reserved										
293	Reserved										
294	Reserved										
295	Flap/Aileron Control Sys. Clearance Inspec.	X	X	X	X	X	X	X			
296	Fuselage Frame Wing Attach Tube Inspection	X	X	X	X	X	X	X			
297	Engine Mount Tube Inspections			X		X					
298	Engine Mount Inspections	X	X	X	X	X	X	X	X	X	
299	Corrosion Inspection	X	X	X	X	X	X	X	X	X	
300	Elevator Trim Actuator Mounting Bracket									X	
	and Clamp Assembly										
301	Proper Tiedown Procedures	X	X	X	X	X	X	X	X	X	
302	Recessed Grab Handle Inspection			X	X	X	X	X	X		*
303	Py Line-Generator Interference					X		X			
304	Special Purpose Operating Weight	X	X	X	X	X	X	X			
305	PT6A Accessory Drive Drain Line Oil Leaks					X		X		X	
306	Engine Plenum Drain Hole Clearance					X		X	X	X	
307	Air Conditioner Drive Pad Assembly									X	
308	Boom Pressure Sensor Orifice					X		X	X	X	
309	Rear Seat Air Conditioner Duct									X	
310	Engine Driven Low Pressure Fuel Pump									X	
311	PT6A-67F Data Plate Replacement									X	
312	Goodrich Starter Generator			X		X		X	X	X	
313	Aileron Torque Tube Bearings-802									X	
314	Fuel Filter Clearance Hole									X	*
315	Fuel System Ice Inhibitors	X	X	X	X	X	X	X	X	X	*
316	Emergency Door Release Spring Bracket				X	X		X	X	X	
317	Rudder Controls Inspection & Maintenance	X	X	X	X	X	X	X	X	X	
318	Upgrades to FCU Override Control Handle			X		X		X	X	X	
319	Bird Strikes on Horizontal Tail	X	X	X	X	X	X	X	X		
320	Environmental Limitations of Air Tractor Ram					X	X	X	X	X	
	Air Engine Induction										

* Indicates Revision

SNOW ENGINEERING CO. Wichita Falls, Texas		ENGINEERING REPORT ORDER								NUMBER 01	
										MODEL All	
TITLE SERVICE LETTER INDEX		BY Leland Snow		CHK'D						SERIAL All	
		DATE *12/30/19								PAGE 10 OF	
		APPLICABILITY									
S/L No.	SUBJECT	300 301	302 302A	400 400A	401 401B	402 402A 402B	501	502 502A 502B 503A 504	602	802 802A	
321	Securing the Cover Plate on the Engine Filter					X	X	X	X	X	
	Pressure Switch										
322	Cockpit Door Emergency Release Handle Stop				X	X		X	X	X	
323	Cockpit Door Emergency Release Alternate				X	X		X	X	X	
	Handle										
324	United Instruments, Inc. 5934 Series	X	X	X	X	X	X	X	X	X	
	Altimeters & 7(1)00 Series (1)VSI Instruments										
325	Hopper Markings				X	X	X	X	X	X	
326	Slips & Falls While Entering, Exiting or Servicing	X	X	X	X	X	X	X	X	X	
	Planes*										
327	Chafing of the Flexible Py Air Signal Line on the							X	X	X	
	Air Conditioner Compressor										
328	Differential Torque Pressure			X		X		X	X	X	
329	Rudder Pedal Attach Assembly								X	X	
330	RCA 2600-3 Digital Horizon Retrofit	X	X	X	X	X	X	X	X	X	*
331	Upper Rudder Hinge					X		X	X	X	
332	Brake Master Cylinder Eyebolt and Clevis	X	X	X	X	X	X	X	X	X	
333	Grab Handle Above Windshield							X		X	
334	Landing Gear Service Life	X	X	X	X	X	X	X	X	X	
335	Engine Mount Inspections									X	
336	Install of New Balance Weight, Support Plates									X	
	Engine Ground Wire Support of BOV PX Line										
337	Loose Items in Cockpit	X	X	X	X	X	X	X	X	X	
338	Flap Actuator Motors								X	X	
339	Retrofit of Engine Air Filter Element					X		X			
340	Post Maint of Flight Control System Continuity	X	X	X	X	X	X	X	X	X	
341	Throttle Quadrant Friction Adjustment	X	X	X	X	X	X	X	X	X	
342	Replacement of A/C Compressor Drive Pad Assy					X					
343	Fuel Drain Valve Damage					X		X			
344	Replacement of Nonconforming Diaphragm	X	X	X	X	X	X	X	X	X	
	Assemblies in Affected Altimeters										
345	Rudder Pedal Attachment								X	X	
346	FAA Airworthiness Directive (AD) 2016-05-13							X	X	X	
	Repl. of Woodward FCU on Certain PT6A Eng.										
347	Flap Torque Tube	X	X	X	X	X	X	X	X	X	
348	Retrofit of Donaldson P609713 Pleated Filter							X	X	X	
	Elem. To AC with Brack. BA-413EFoam Filter El										
349	MVP-50T Disabling Master Caution & Master							X	X	X	
	Warning Lights Assc. w/Propeller RPM(NP)										
350	Torque Gauge Filling With Engine Oil			X		X		X	X	X	

* Indicates Revision

SNOW ENGINEERING CO. Wichita Falls, Texas		ENGINEERING REPORT ORDER								NUMBER 01	
										MODEL All	
TITLE SERVICE LETTER INDEX		BY Leland Snow			CHK'D					SERIAL All	
		DATE *12/30/19								PAGE 11 OF	
		APPLICABILITY									
S/L No.	SUBJECT	300 301	302 302A	400 400A	401 401B	402 402A 402B	501	502 502A 502B 503A 504	602	802 802A	
351	Pneu. Emergency Dump Sys. Pres. Gauge With									X	
	Potential Erroneous Reading Correct. Action							X	X	X	
352	Installation of Power Quad. Anti-Reverse Fence							X	X	X	
353	AT-504 Airspeed Indicators							X			
354	MVP-50T G-Force Sensor Calibration			X		X		X	X	X	
355	Install. of Power Quad. Anti-Reverse Fence504							X			
356	Install. of Power Quad. Anti-Reverse Fence402					X					
357	Tail Wheel Axle Bolt								X	X	
358	Seat Frame	X	X	X	X	X	X	X	X	X	
359	Vertical Fin Rear Spar Attach					X		X	X	X	
360	Replacement of Woodward Overspeed Governor							X			*
361	Fuel Filter Sealing Washers			X		X		X	X	X	
362	Owner's Manual Recommendations for PT6A-			X		X		X	X	X	
	Engine Maintenance										
363	Pacific Propeller Intl. LLC P/N:6101A-12 Blade	X			X						
	Assembly Taperbore Shotpeen										
364	Dangers of Using Propeller Beta in Flight			X		X		X	X	X	
365	Installation of the 53404-1 Engine Air Filter					X		X			
366	Aileron Bell Crank Support Inspection									X	
367	Flap Drive Actuator Arm Chafing on Fuel Hose							X			
368	AT-502A Chip Detector w/MVP-50T Engine							X			
	Monitor System										
369	51198-1 Pulley Shaft					X		X	X	X	
370	Brake Master Cylinder Upper Mounting Hole	X	X	X	X	X	X	X	X	X	
371	Reserved										
372	Reserved										
373	Installation of the Surelock Tail Wheel Lock					X		X	X	X	
374	Bleed Air Loss	X	X	X	X	X	X	X	X	X	
375	Flap Motor Mounting Studs								X	X	
376	Flight Operations While Using Avgas Fuel			X		X		X	X	X	
377	Modifications to Air Tractor Airplanes	X	X	X	X	X	X	X	X	X	
378	Change in Preferred Grease for Hartzell	X	X	X	X	X	X	X	X	X	
	Propellers										
379	Cleaning Plastic Window Transparencies	X	X	X	X	X	X	X	X	X	

* Indicates Revision